

QuickDraw GX: Non-Native Error on Reformatted Drive (2/95)

Article Created: 15 November 1994 Article Reviewed/Updated: 16 February 1995

TOPIC -----

I have a Power Macintosh and have reformatted the Apple internal hard drive with APS Power Tools version 2.8.2. I then installed QuickDraw GX after installing 7.5. I am now getting an error message that says the non-native version of QuickDraw GX is installed.

I reformatted the hard drive with Apple HD SC Setup and QuickDraw GX worked fine.

DISCUSSION -----

We found a similar problem with APS version 3.0.1. Version 2.8.2 of the APS Power Tools utility was written by a company called Transoft. We called Transoft and APS to inform them of this problem. Technical support at Transoft said the only problem they found was the Color Picker problem: the error "Insert <hard disk>" shows up if virtual memory is turned on and goes away when Virtual Memory is turned off when accessing the Color Picker. Transoft technical support said that no one had called them with the QuickDraw GX problem. APS said that no one had called them with the problem.

Transoft had a fix for the Color Picker problem. There is a control panel that comes with APS PowerTools called "Power Tools Assistant 1.5.7". This control panel allows the user to change options about the drive. The interface is like the Startup Disk control panel where you select the drive and then click the option button. One of the options is "Disable Finder Eject." When this option is selected, both the Color Picker and the native GX problem go away.

We tried to duplicate the problem with APS software version 3.0.5 and could not do it. This could indicate that the problem only exists with the 3.0.1 version. Contact APS for an upgrade.

Note:

This article provides information about a non-Apple product. Apple Computer, Inc. is not responsible for its content. Please contact the vendor for additional information.

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

Tech Info Library Article Number: 16773