



# Tech Info Library

## Multimedia Starter CD Asks For Install Disk 2 (2/95)

Article Created: 22 February 1995

TOPIC -----

This article describes how the Multimedia Starter CD asks for "Install Disk 2" while installing the Hardware System Update (HSU) 2.0 included on the CD.

DISCUSSION -----

The Multimedia Starter CD comes with every Multimedia Kit, and it contains a folder called Macintosh System Updates. A user is instructed to Install HSU 2.0 on their system as part of the process. There is an Installer in the Macintosh System Updates folder which users are supposed to run. When a user runs this installer, he or she may be instructed to insert Install Disk 2, but there is no Disk 2.

If a user has already installed System 7.5, HSU 2.0 DOES NOT need to be installed.

A workaround is to view the Macintosh System Update folder by name under the View menu, and look for a folder called, Extensions and Control Panels. The contents of this folder can be moved by selecting the folder contents and dragging them to the active System folder.

Support Information Services  
Copyright 1995, Apple Computer, Inc.

Keywords: ksts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 17252