



# Tech Info Library

## Macintosh System Update 2.0.1: Description (10/93)

Article Created: 4 October 1993

TOPIC -----

System Update 2.0.1 contains enhancements to Macintosh System 7.1 and System 7 Pro and a collection of bug fixes. This update requires Macintosh System Software version 7.1 or System 7 Pro.

DISCUSSION -----

Macintosh System Update 2.0.1 incorporates enhancements from the two previous versions of the Hardware System Update, versions 1.0 and 2.0. The primary additional enhancements that Macintosh System Update 2.0.1 provides are:

- Apple HD SC Setup version 7.2.2, which gives you more flexibility to format large Apple hard disks between 1 and 2 gigabytes.
- AutoRemounter 1.2, which significantly reduces network traffic.
- Apple Disk First Aid 7.2, a utility that repairs damaged disks, which provides a new user interface.
- More efficient management of the way fonts use memory.
- Macintosh PowerBook Control Panel version 7.1.3 and Express Modem software version 1.1.2, which include support for communications software that doesn't use the Apple Communications Toolbox.
- System Enabler 131 (version 1.0.3) for the PowerBook 160, 165, 165c, and 180 to support 12-inch monitors and improve reliability.
- Support for System 7.1.1.

The Apple Macintosh System Update will be licensed to customers free of charge through various on-line services, including AppleLink, America Online, and CompuServe. The System Update 2.0.1 extension will also be included in System 7 Pro, and will be placed directly onto hard drives of shipping CPUs.

Copyright 1993, Apple Computer, Inc.

Keywords: SUPT,specsht

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 13366