



Tech Info Library

AppleCD Audio Player: Volume Setting Aren't Retained (7/96)

Article Created: 19 July 1996

TOPIC -----

I am using the AppleCD Audio Player v2.1, which came with System 7.5.3 Update 2.0, and cannot find a way to make the AppleCD Audio Player retain the volume settings after I restart my Macintosh computer.

DISCUSSION -----

This issue has been reported to Apple Engineering and they are investigating a solution. Currently the only solution is to reset the volume slider to the desired position.

When you restart your Macintosh the AppleCD Audio Player v2.1 slider defaults to the middle position, so you must manually change the volume each time you use the AppleCD Audio Player.

Copyright 1996, Apple Computer, Inc.

Keywords: sys7.5

=====

This information is from the Apple Technical Information Library.

19960722 19:30:46.00

Tech Info Library Article Number: 20184