



Tech Info Library

Hardware System Update 2.0 & Display of Control Panels (8/93)

Article Created: 6 August 1993

TOPIC -----

I recently installed the Hardware System Update 2.0 on my Macintosh. Now, some of the control panels (like NOW Menus, Remote Access Setup, and Startup Manager) have their top lines cut off. Also, the text displayed in the pop-up menus of the control panels was 12 point instead of the usual, smaller size.

DISCUSSION -----

A possible solution in this situation is to reset the Parameter RAM (PRAM) of your system. Do this by holding down the four keys Command, Option, P, R immediately upon startup until you hear the startup chime for the second time. Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12919