



Tech Info Library

Macintosh Portable: Developer Issues on MIDI Support

Article Created: 14 June 1990

Article Last Reviewed: 14 May 1992

Article Last Updated: 14 May 1992

TOPIC -----

I was told there were some problems with MIDI software on the Macintosh Portable at introduction. What is the current status of this? What is Apple doing to fix the problems? What must a developer do?

DISCUSSION -----

The only change since introduction is that most developers have provided an update to their software or have begun using Apple's MIDI Manager, or both. There are two support issues to be aware of when using an older version of MIDI Manager (1.1) and the Macintosh Portable. Both issues relate to the implementation of the serial ports of the Macintosh Portable.

1) Version 1.1 of the MIDI Management Tools does not support the Macintosh Portable.

MIDI Management Tools version 1.1 required changes to work correctly with the serial ports of the Macintosh Portable. These changes were implemented in version 1.2 of the MIDI Management Tools.

2) Some older versions of third party MIDI applications will have difficulty with the Macintosh Portable.

Until the introduction of Apple's MIDI Manager, all MIDI software had to write to the serial port hardware directly, bypassing the Macintosh Toolbox, to obtain acceptable performance. Writing to the hardware is not an ideal procedure for developers; Apple changes things about the hardware from one Macintosh model to the next. This forced MIDI software developers to revise their programs every time a new Macintosh model was introduced.

With the changes in design of the Macintosh Portable, these direct hardware calls and Toolbox workarounds no longer perform as they would on earlier models of Macintosh. Fortunately, Apple resolved this issue by providing the MIDI Manager. If developers use the MIDI Manager, they will not need to revise their programs as a result of any serial port changes in future computers. MIDI Manager will be revised as needed to deal with changes in serial ports. With

MIDI Manager 1.2 or later, applications supporting MIDI Management Tools work correctly on the Macintosh Portable.

Make sure to use the most current version of the MIDI Manager to ensure that a program will communicate successfully with the serial port, regardless of Macintosh model.

Copyright 1990, 1992 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 5815