



# Tech Info Library

## HD Setup: Differences Between Version 2.0.1 and 2.0.3

Article Created: 13 August 1991

Article Last Reviewed:

Article Last Updated:

TOPIC -----

I need to find out what the differences are between HD Setup 2.0.1, 2.0.3 and the HD Setup for System 7.0B4.

I am especially interested in how initialization and bad sector mapping have changed and about reentrance code and where it resides on the drive.

DISCUSSION -----

The differences between 2.0.1 and 2.0.3 were very minor minor bug fixes that never did crop up in normal use but the engineers knew they were there and fixed them anyway.

For the System 7 driver, it was modified to include a reentrant driver for support of virtual memory. The driver is written to the disk very early in the boot process to a portion of the drive to which we, as users, do not have access.

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8622