



Tech Info Library

Drive Setup 1.0.3: May Report Incorrect Version (1/96)

Article Created: 8 December 1995

Article Reviewed/Updated: 2 January 1996

TOPIC -----

This article describes an incorrect version number being reported when using Drive Setup 1.0.3.

DISCUSSION -----

The Drive Setup 1.0.3 software that ships with the PowerBook 2300c, and may be included in other systems with IDE disk drives, may show an incorrect version number of "1.12e3" in the Get Info window of the IDE disk drive. This incorrect version number was inadvertently left in the final version of Drive Setup 1.0.3 which has no affect on the software's functionality.

Article Change History:

02 Jan 1996 - Made minor technical update.

Support Information Services

Copyright 1995-96, Apple Computer, Inc.

Keywords: ksts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 19053