



Tech Info Library

Apple Macintosh Portrait Display: Adjustment Magnet Kit (11/94)

Article Created: 22 April 1991

Article Reviewed/Updated: 08 November 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I have an Apple Macintosh Portrait Display. My initial problem was a brown spot in the center of the screen. After I replaced the CRT assembly raster, there was a drop of about 1/8-inch from left to right on the upper-horizontal edge of the raster. I tried adjusting the horizontal height and vertical pin cushion, but this didn't help.

DISCUSSION -----

You can adjust this type of distortion by installing the Portrait Display Adjustment Magnet Kit (service part number 949-0253). The Additional Procedures section of the Portrait Display section of the Service Source CD details the installation of this kit. If you do not want to replace the CRT again, this is the kit you need.

Article Change History:

08 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7642