



# Tech Info Library

## AV Display: No Raster with 660AV & 840AV (10/93)

Article Created: 20 October 1993

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

### TOPIC -----

I have a Macintosh 660AV and an 840AV. When I connect the AudioVision 14 Display to either of these two AV computers, the AV monitor produces NO RASTER. The green LED lights up and the I hear high voltage.

Here's what I have tried so far: I have used a Basic Color Monitor and a Monochrome 12" on the AV computers and they worked fine. The monitor also works fine off of a Macintosh II with a 8/24 video card inside.

### DISCUSSION -----

The 660AV and 840AV computers are most definitely compatible with the AV display. Since you have determined that the AV display is functioning with another Macintosh CPU, we can eliminate the monitor as the source of the problem. The CPUs are most likely not at fault because the probability that both the 660AV and 840AV are exhibiting the exact same symptom is extremely remote.

Your problem is a defective video adapter cable.  
Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 13669