



# Tech Info Library

## Daisy Wheel Printer: Forms Tractor Timing Belt Replacement 5/93

Article Created: 21 May 1993

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC -----

I have a Daisy Wheel Printer and I need to replace the timing belt on the forms tractor. I understand there could be 2 different timing belts. What are the differences and how do I order them?

DISCUSSION -----

The Daisy Wheel Printer (DWP) forms tractor timing belt from Apple Service (P/N 970-0537) is 120 speed (120 teeth).

In rare instances, Apple has discovered that some DWP forms tractors require a 126 speed (126 teeth) timing belt, which Apple does not stock.

The manufacturing part numbers for the two timing belts are as follows:

- 120 Speed (120 teeth) 85437-05
- 126 Speed (126 teeth) 85437-02

If a Service Provider is replacing a DWP forms tractor timing belt and requires the 126 speed (85437-05), contact Electronic Repair Company.

To locate a vendor's address and phone numbers, use the vendor's name as a search string.

Copyright 1993, Apple Computer, Inc.

Keywords: supt,3pty, hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12172