



Tech Info Library

LaserWriter II Refurbishment Kit Parts (7/95)

Article Created: 18 July 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

What exactly is in the LaserWriter II Refurbishment kit, part number 652-0597.

DISCUSSION -----

The LaserWriter II Refurbishment kit, part number 652-0597, kit consist of the following:

Part #	Description
661-0440	Fuser Assembly
971-0017	Paperfeed Assembly
971-0019	Transfer Guide Assembly
971-0025	Pre-Cond. Exp. Lamp Assembly
971-0026	Transfer Corona Assembly

Support Information Services
Copyright 1995, Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 18201