



Tech Info Library

Macintosh: 512K SIMM Identification (11/94)

Article Created: 1 August 1991

Article Reviewed/Updated: 10 November 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

How can I identify the vendor of an Apple 512K SIMM (Service part number 661-0646)?

DISCUSSION -----

Apple has three 512K SIMM vendors. To identify the vendor, look on the SIMM PC board for the vendor's part number:

Vendor	Part Number
-----	-----
Samsung	KMM 5812A - 8
Motorola	MCM 84512S
TI	512 - 80L

For an example of an Apple 512K SIMM, see the June '91 Service Module Identification update (page 1.9.9).

Notes

- Apple does not add any unique coding to its SIMMs. Some third parties may provide the same types of SIMMs.
- The 512K SIMMs are available only through Service. They are not available through Finished Goods.

Article Change History:

10 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 7977