



Tech Info Library

Macintosh IIfx Logic Bd Upgrade: Terminator is Included (11/94)

Article Created: 14 June 1991

Article Reviewed/Updated: 10 November 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I've upgraded my Macintosh II to a Macintosh IIfx and am having trouble mounting my internal hard drive. I've been told I need to have a "Macintosh IIfx motherboard terminator and filter" module in line with the 50 pin SCSI data cable. Where do I find this?

DISCUSSION -----

The part you are looking for comes in the Macintosh IIfx Accessory Kit with the Macintosh IIfx Logic Board Upgrade. It's in a little plastic bag and is grey with a beige terminator attached.

You need to remove the beige terminator and place the grey filter between the drive cable and the drive. If you cannot find this part, it can be ordered through Apple Service, part number 590-4516.

Understand that the terminator is required ONLY if no internal SCSI hard drive is installed. If you have a drive installed, you have to remove the terminator to connect the drive cable. Consult the drive manufacturer to determine if the SCSI Filter is required for that particular drive.

Article Change History:

10 Nov 1994 - Reviewed for technical accuracy.

Support Information Services

Copyright 1991-94, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8476