



Tech Info Library

Notions List Manager: Correcting Error -10401 or -10405 (5/94)

Article Created: 23 May 1994

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I get a -10401 or -10405 error inserting a PCMCIA card containing Notions List Manager into my Newton MessagePad. How can I correct this?

DISCUSSION -----

These errors occur if the Notions List Manager package is installed before the template packages.

To correct this problem:

- 1) In the Extras Drawer, Tap the Card icon
- 2) Tap remove software and remove all Notions List Manager templates on the PCMCIA card.
- 3) Reinstall the templates using the Newton Connection Kit.

These errors only occur with Notions List Manager installed on a PCMCIA card. You will not get these errors with the package installed in the Newton MessagePad's internal memory.

Support Information Services
Copyright 1994, Apple Computer, Inc

Keywords: knmp

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 15416