



# Tech Info Library

## Ofoto 2.0: Eraser Tool Line Artifacts Bug (10/93)

Article Created: 21 May 1993

Article Reviewed/Updated: 18 October 1993

\* RESTRICTED: Apple Internal and Support Providers Only \*  
Not For General Public Release

TOPIC-----

I'm experiencing a problem with Ofoto 2.0 and the Color OneScanner. After an image is scanned in (B&W) and the eraser tool is used to remove some elements, line artifacts appear in the darker parts of the scanned image. These line artifacts are in the same horizontal plane as where the eraser tool was used.

As a workaround I'm saving the image as scanned and editing in PhotoShop.

DISCUSSION-----

The eraser tool issue was a problem with the first release of Ofoto 2.0. Light Source has corrected it, and released Ofoto Version 2 update 2.0.2 for Apple scanners. This update has been mailed to everyone who bought the Ofoto Version 2 upgrade for Apple scanners directly from Light Source. In addition, the update will be sent to new Apple scanner owners who register Ofoto before October 31, 1993. If you have Ofoto release 2.0 and an Apple scanner, and you would like the revision, please mail in your registration card before October 31, 1993, and it will be sent to you automatically.

After October 31st, call Light Source at 800-231-7226 to order the update for an \$8 shipping charge. Outside the United States and Canada, call Light Source in Scotland at 44-506-462-444 (shipping is \$25). Be sure to have your Ofoto disks handy.

Please note that Light Source Technical Support now has its own AppleLink address: LS.SUPPORT

Article Change History:

18 October 1993 - Added update 2.0.2 availability information.

7 September 1993 - Changed audience from Apple only.

16 August 1993 - Contacted Light Source to verify that the new revision is available.

Copyright 1993, Apple Computer, Inc

Keywords: KSTS

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12176