



Tech Info Library

PowerBook 145B: Disk Tools Diskette Error Message (7/93)

Article Created: 30 July 1993

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

When inserting the Disk Tools diskette into a PowerBook 145B, a message comes up saying that the desktop folder on the startup disk could not be created.

DISCUSSION -----

About 10,000 PowerBooks 145B models made by Acer (serial number starts with EE) have bad Disk Tools floppies.

There is a simple workaround. Unlock the diskette, insert it, let it mount (or boot up). Eject the disk, relock it, and the message will not come up again.
Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 12831