



Tech Info Library

Performa 6360, 6400: Performa Demo and Error -108 (3/97)

Article Created: 3 March 1997

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I have a Performa 6360. I recently upgraded its system software from 7.5.3 to 7.5.5. Now when I run the Performa Demo program and try to launch the "Sign-Up With Apple" program, the system bombs with an error -108 on the screen. What is wrong? How can I fix this?

DISCUSSION -----

The behavior you describe occurs because there is not enough memory available to run the two programs simultaneously.

If the system software is updated to 7.5.5 on either a Performa 6360 with 16 megabytes of RAM or a Performa 6400 with 16 megabytes of RAM, the memory used by the system software (known as the system heap) increases just enough to prevent both the Performa Demo and "Sign-Up With Apple" applications to run simultaneously.

To run both the Performa Demo and the Sign-Up With Apple programs simultaneously under System 7.5.5, either install additional RAM or turn on virtual memory, making sure that total memory is set to at least 17 megabytes.

Copyright 1997, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

ArticleID: TECHINFO-0021058

19970304 08:21:56.00

Tech Info Library Article Number: 21058