



Tech Info Library

System 7: Limited Support for PATHWORKS 1.0 (1/95)

Article Created: 10 September 1991

Article Reviewed/Updated: 31 January 1995

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

I am running PATHWORKS 1.0a, and just upgraded to System 7. The Macintosh IIcx 8/160 won't start up with the DECnet drivers installed. I first get the "coprocessor not installed" error, then it changes to a "bus error" message. If I take DECnet out, it works fine. I also took out all other INITs to make sure it's not an INIT conflict.

DISCUSSION -----

System 7 does NOT support PATHWORKS For Macintosh version 1.0, although most of the components do work properly. Release 1.1 of PATHWORKS for Macintosh provides full System 7 support as well as performance and functionality enhancements.

Article Change History:

31 Jan 1995 - Noted version which is System 7 compatible, changed access.

Support Information Services

Copyright 1991-95, Apple Computer, Inc.

Keywords: knts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8883