



Tech Info Library

SCSI Terminators M0209 & M0332LL/A: Differ Only In Color (2/93)

Article Created: 18 February 1993

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

What is the difference between the older SCSI Terminator (Part Number M0209) and the new SCSI Terminator (Part Number M0332LL/A)?

DISCUSSION -----

The only difference between these SCSI Terminators is their color. Part Number M0209 is Smoke color and Part Number M0332LL/A is Platinum color.

There is no electrical or performance difference between these SCSI terminators.

Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 11531