



Tech Info Library

Service Notice: Ethernet Twisted-Pair NB Card (10/93)

Article Created: 21 October 1993

* RESTRICTED: Apple Internal and Support Providers Only *
Not For General Public Release

TOPIC -----

This article is a Service Notice for the new Apple Ethernet NB Twisted-Pair Card.

DISCUSSION -----

Overview

The Apple Ethernet NB Twisted Pair Card connects a Macintosh computer to an Ethernet network using an IEEE 10Base T standard RJ-45 port. With 128 kilobytes of RAM, this card transfers data up to 10 megabits per second. Note that the RJ-45 cable is not supplied with the card because of different installation requirements at customer sites.

Technical Information

Technical and troubleshooting information for the Apple Ethernet NB Twisted Pair Card is on "Service Source" CD (Path: Networks & Comm., Ethernet & LocalTalk Products). Module Identification will be included in the November update to the "Apple Service Guide for Module Identification."

Ordering Parts

Apple Authorized Service Providers planning to support the Apple Ethernet NB Twisted Pair Card may purchase Service modules to develop servicing capability. To order, use the AppleOrder system. Or, refer to the TBD Service Prices and then fax (512-919-2950) or phone (512-919-2775) U.S. Customer Service.

Warranty and AppleCare

The Apple Ethernet NB Twisted Pair Card is covered under the Apple One-Year Limited Warranty. The AppleCare Service Plan is also available for the card. For part number and pricing information refer to the AppleCare Service Prices. Service Providers are reimbursed for warranty and AppleCare repairs made to this card.

Copyright 1993, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 13730