

## StyleWriter 1200: No Replacement Cut Sheet Feeder (12/96)

Article Created: December 17, 1996

\* RESTRICTED: Apple Internal and Support Providers Only \* Not For General Public Release

TOPIC -----

In the Troubleshooting section of the StyleWriter 1200, the Service Source CD points to a replacement part for a Cut Sheet Feeder, which is not available as a Service Part. Is this part available, or is this a mistake in the Service Source CD?

DISCUSSION -----

The Service Source CD has incorrect information concerning the Cut Sheet Feeder replacement part for the StyleWriter 1200 printer. There is no service part available for the Cut Sheet Feeder on this printer. If the problem is isolated to this part of the printer, the only option is a whole unit exchange. This will be corrected in the upcoming release of the Service Source CD.

Copyright 1996, Apple Computer, Inc.

Keywords: <None>

\_\_\_\_\_

This information is from the Apple Technical Information Library.

19961218 09:46:46.00

Tech Info Library Article Number: 20738