



# Tech Info Library

## Newton: System Update 1.05 Changes and Features (2/94)

Article Created: 23 February 1994

Topic -----

What features does Newton System Update 1.05 provide?

Discussion -----

There are a number of updates including the following:

### Dates

-----

Addresses problems with recurring meetings

- Exception repeating meetings alarms

- 48009 error when deleting exceptions to recurring meetings

Alarms for appointments on a card after reset

Removes error that indicates "styles slot is too short" in to do list

### Restore

-----

Removal of false error when starting up

A card with packages problem

Allows restore from a card with too big a backup

Restores Letter styles properly

### Beaming

-----

Fixes "Auto receive"

Multiple beams problem

### Power Faults

-----

Alleviates system sensitivity to power fluctuations on wakeup

Unit can now always turn off

### Memory Management

-----

Elimination of memory fragmentation and leaks

Increase of system memory by 32K

Time Zones	Old	New
-----	-----	-----

Singapore	+7:30	+8:00
Anchorage	-10:00	-9:00
Tientsin	+8:30	+8:00
Mt. Everest	+5:30	+5:45

Word List

-----

List now scrolls

Words that start with a capital letter can now be removed

Warm Reset

-----

When switching folders and restarting, scrolls to the end of the notepad

Backup

-----

Backup can be completed regardless of how full the internal memory is

Modem

-----

Addresses out of sync wait for answer setting

Modified modem level for Japan approval

Dialing Assistant

-----

Outgoing code for Hong Kong corrected

Corrects incorrect prefixes for Hong Kong, Singapore, and other cities

Support Information Services

Copyright 1994, Apple Computer, Inc

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 14701