



Tech Info Library

CD Speed Switch: Compatibility With 68LC040 Computers (4/95)

Article Created: 29 March 1994

Article Reviewed/Updated: 05 April 1995

TOPIC -----

I have a LC 475 with an external AppleCD 300 drive. When sound is played from my Time Almanac CD, the sound is choppy. When I double-click on the CD Speed Switch Control Panel, as explained in Apple's documentation, I get a message that the control panel can't be used on that model of Macintosh.

DISCUSSION -----

There are two separate issues involved in this situation. First, the AppleCD Speed Switch software is not compatible with computers using the 68LC040 microprocessor. This includes the LC 475, 476, 575, Quadra 605, Quadra 610, and many PowerBook models. Check the specification sheet for your computer to verify it it has a 68LC040 processor.

You should install version 5.0 or greater of the CD-ROM software for the CD-300 external drive. This version is fully compatible with the LC 475 and has the equivalent of the Speed Switch integrated into the driver. This version of the CD-ROM driver has been tested with the LC 475 and it works just fine, it did not solve the choppy sound problem however.

The second issue revolves around the Time Almanac CD itself. Testing the Time 1993 Almanac with the LC 475 produced the same audio results as the you encountered. Playing the Almanac's movies with the Apple MoviePlayer program works fine. So, it seems that the problem was with the Time Almanac application.

Compact Publishing, Inc. said they were aware of the problem and are working on a patch to resolve it. Contact them directly to receive the patch when it becomes available.

To find the latest version of the CD-ROM software, search for these articles:

- Where To Find Apple Software Updates
Lists online services for "free" Apple software updates
- Obtaining Apple Product Support in the USA
Lists 800 numbers and online services for software updates, Apple support information, and a subset of the Apple Tech. Info. Library

Article Change History:

05 Apr 1995 - Added Centris 610 to list of 68LC040 computers

05 May 1994 - Made article more generic on version numbers and on-line software resources.

Support Information Services

Copyright 1994-95, Apple Computer, Inc.

Keywords: kcompat

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 14966