



# Tech Info Library

## Macintosh II Family: Monitor Noise at Startup is Normal

Article Created: 14 June 1991

Article Last Reviewed:

Article Last Updated:

TOPIC -----

Many Macintosh II monitors make a loud noise when powering up. The high-resolution monochrome and color models seem to make this noise consistently. Is there a problem with these monitors, or is this just a characteristic of the monitor?

DISCUSSION -----

The sound that you hear is the degaussing coil being activated on power-up. Color monitors are subject to impurities from other magnetic fields. This is countered by putting a neutralizing field around the front of the CRT on power-up or by pressing the degaussing coil button on the back of the monitor.

The sound is simply the coil energizing and is in no way a sign of current or future problems.

Copyright 1991 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 8434