



# Tech Info Library

## Apple IIgs: Cable Compatibility (10/94)

Article Created: 27 September 1994  
Article Reviewed/Updated: 27 October 1994

### TOPIC -----

This article provides cable compatibility information for Apple computer systems and a variety of Apple peripherals.

The left column lists the peripherals, the right column lists the cable required to connect one of the following computers to it; Apple IIgs, or the Apple IIgs upgrade.

Part numbers which begin with a letter are the finished goods part number, the seven digit numbers are the service part numbers.

### DISCUSSION -----

| Peripheral<br>-----  | Cable part number<br>-----                             |
|--|--|
| AppleFax Modem   | N/A  |
| Apple Personal Modem<br>Apple Data Modem 2400                              | M0197/590-0552 (smoke)                                 |
| Apple Modem 300<br>Apple Modem 1200  | A2C0354/590-0121% & 590-0550<br>or 590-0197 & 590-0553 |
| Apple ImageWriter II or II/L<br>Apple ImageWriter LQ                       | M0197/590-0552 (smoke), LocalTalk<br>optional          |
| Apple ImageWriter Printer<br>Apple ImageWriter 15"<br><br>A9M0333/590-0550 | M0150/590-0169 & 590-0553<br>or<br>A2C0352*/590-0037 & |
| LaserWriter, Plus, IInt, IIntx, IIif, IIg                                  | LocalTalk  |

LaserWriter Pro 600/630/810  
Personal LaserWriter NT, NTR

Personal LaserWriter LS \*  
StyleWriter & StyleWriter II  
Color StyleWriter/Color StyleWriter Pro

Apple LaserWriter IIsc N/A  
Personal LaserWriter SC

AppleCD SC M0206/658-8031•  
Apple Hard Disk 20/40/80

Apple Tape Backup 40SC N/A  
Apple Scanner  
Apple Color OneScanner  
Apple Color Printer

LEGEND

- Requires M3503LL/B/658-8032 Cable Terminator
- \* The Apple IIgs with GS/OS ver. 6.0 will support the original StyleWriter only.

A9M0320 or A3M0025 w/590-0037 require Super Serial Card BUT A9M0302 or A3M0025 w/590-0037 & 590-0550 doesn't (Buses Built In).

When using an ImageWriter II/LQ with the Apple IIe and cable part number 590-0555, the jumper on the Super Serial Card must be on "Modem".

Article Change History:

27 Oct 1994 - Indicated that StyleWriter is supported by GS/OS ver. 6.0.

Support Information Services  
Copyright 1994, Apple Computer, Inc

Keywords: ktable,cabinfo,review

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 16384