



Tech Info Library

800K Floppy Drives: Don't Use with Old Hewlett-Packard 3.5 Disks

This article last reviewed: 10 November 1987

A word of caution to those who try to use the old HP 3-1/2" disks (i.e., the ones that don't have springs; you have to open and close the shutter by hand) in the 800K Macintosh and UniDisk 3.5 drives.

An old HP disk has a protective door which locks in the open position when it is opened all the way. An Apple 400K drive doesn't slide the door all the way open, and so it doesn't lock in the open position.

However, an Apple 800K drive does slide the door all the way open, and because the protective door locks, the drive isn't able to eject the disk.
Copyright 1988 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 1997