



Tech Info Library

HayesConnect 1.0C: Corrects Hang Problems of 1.0B

This article last reviewed: 9 August 1989

TOPIC -----

I have a problem running the Hayes Modem serving software on our AppleShare File Server. Here is the configuration:

Server: Macintosh IICx with 4MB RAM
Software: AppleShare 2.0.1
Timbuktu 2.0.1 f2
HayesConnect 1.0B

The system hangs in AppleLink and in MacTerminal communications. The server also hangs and has to be reset. Why?

DISCUSSION -----

The problem is probably with HayesConnect, version 1.0B. Contact Hayes Technical Support group for an update to HayesConnect 1.0C, which should correct this problem.

For more information, search under: Hayes Microcomputer
Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 4051