



Tech Info Library

Color OneScanner Dispatcher Software: Auto Straighten Issue 7/96

Article Created: 9 July 1996

TOPIC -----

Scanning with Automatic Straighten feature does not always give good results. The scanned image is sometimes rotated 30-45% or more, and the scaling may be incorrect.

DISCUSSION -----

Both the v1.0 and v1.0.2 versions of the Apple Color OneScanner Dispatcher Software sometimes do not perform the Automatic Straighten function correctly. One workaround that sometimes helps is not to place the original image adjacent to the alignment mark and rulers. The other workaround is not to use the Automatic Straighten feature if you encounter this problem.

Copyright 1996, Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960710 07:01:34.00

Tech Info Library Article Number: 20150