



# Tech Info Library

## LaserWriter Iintx: Don't Try To Put Macintosh II SIMMs In It

This article last reviewed: 10 February 1988

There is no way to plug a Macintosh II SIMM into a LaserWriter IINTX, or vice versa. The two SIMMs are incompatible both physically and electrically.

The LaserWriter IINTX SIMM is .25" longer than a Macintosh II SIMM.

The LaserWriter IINTX SIMM has 128 contacts on the module, in four groups of 32 (64 on each side).

The Macintosh II SIMM has 60 contacts, 30 on each side of the module.  
Copyright 1989 Apple Computer, Inc.

Keywords: <None>

=====  
This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 2536