



# Tech Info Library

## LW IINTX ROM Upgrade: Wrong Font Utility Shipped

This article last reviewed: 9 October 1990

TOPIC -----

My LaserWriter IINTX ROM Upgrade Kits has version 1.0 of the LaserWriter Font Utility. Shouldn't I have gotten version 2.0?

DISCUSSION -----

Many of the LaserWriter IINTX ROM Upgrade Kits have been shipped with version 1.0 of the LaserWriter Font Utility. They should have included version 2.0. This is a known problem in the build process. Currently shipping units should have version 2.0. However, if you received the wrong version, version 2.0 is available on AppleLink in the Apple Software Updates board. Use this path:

Apple Software Updates  
  Macintosh  
    Peripheral System Software  
      Apple LaserWriters  
        Personal LaserWriter NT  
          Installation Disk  
          Other  
Copyright 1990 Apple Computer, Inc.

Keywords: <None>

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 6196