



# Tech Info Library

## LaserWriter IIf/IIg: Add RAM to Correct Margin Problems (2/95)

Article Created: 26 March 1992

Article Reviewed/Updated: 06 February 1995

TOPIC -----

I have margin problems when printing to the LaserWriter IIf and IIg.

DISCUSSION -----

The LaserWriter IIf now ships with 4MB and the LaserWriter IIg ships with 8MB of DRAM. These configurations will improve the margin problems and some memory management problems.

If your printer has similar problems, the memory can be upgraded to these levels to resolve the problem. See your authorized Apple service provider for the upgrade.

Article Change History:

06 Feb 1995 - Reviewed for technical accuracy.

Support Information Services

Copyright 1992-95, Apple Computer, Inc.

Keywords: hts

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 10002