



Tech Info Library

Applied Engineering (6/95)

Article Created: 3 December 1988

Article Reviewed/Updated: 6 June 1995

Applied Engineering

3210 Beltline Rd.
Dallas, TX 75234

Company Profile:

Applied Engineering went out of business in May 1994. They made hardware, specializing in Apple II & Macintosh peripheral boards. Tech support for some of their products is now being handled by a few separate companies.

Accelerators

=====
Brainstorm Products
Provides support for Applied Engineering accelerators and related software only.

Apple II Related Products

=====
ABC Direct
** FOR SCHOOLS OR BUSINESSES ONLY. NO INDIVIDUALS PLEASE **
Provides support for the Applied Engineering products for the Apple II series (including the DOS compatibility card). Also has a repair service available for any Applied Engineering product based on an hourly fee.

Parallel Printer Interface Cards

=====
Orange Micro, Inc.
Offer solutions to many problems with Applied Engineering parallel printer interface cards (similar to their own Grappler boards).

The Tech Info Library article titled "Locating Vendor Information" can help you search for a particular vendor's address and phone number.

Article Change History:

06 Jun 1995 - Added information about Orange Micro, Inc.
10 Feb 1995 - Added reference to Locating Vendor Info article.

Support Information Services
Copyright 1989-95, Apple Computer, Inc.

Keywords: 3pty

=====

This information is from the Apple Technical Information Library.

19960215 11:05:19.00

Tech Info Library Article Number: 3354